SERVICE REPORT

JOB NO : 2727 0 3 – 0 0 1 4 5

Customer PRICON MICROELECTRONICS. INC.	Date July 27, 2016
Person-In Charge MR. E. GAMBOA Dept ENGG.	P.O. No
Tel Fax	Remark SV-1606017R1

Job Title MACHINE INSPECTION

Model S/No Instal/Date

Problem

Measures

5-UNITS OF AIDA PRESS MACHINE HAVE BEEN DONE ANNUAL MACHINE INSPECTION.

M/C No. 1 - NC1-45(2) S/N 00204-6220 TUC OIL LEAKS.
Mk No. 2 - NC1-45(2) S/N 10204-7197
Mk No. 3 - NC1-80(2) S/N 10208-8797 TUC OIL LEAKS.
Mk No. 4 - NC1-80(2)-B S/N 00208-5727
Mk No 5 - NC1-80(2) S/N 00208-7119 BOLSTER FLATNESS NG NEED TO GRIND

NOTE: 1) OTHER MECHANICAL ISSUE ARE MINOR PROBLEM LIKE, AUTO DRAIN FILTER, AUTO GREASE PUMP, V-BELT. AND SOLENOID VALVE FOR C/B OVER 3-YEARS. MAX. LIFE FOR PRESS MANNUAL OPERATION
2) FOR ELECTRICAL ISSUE, NEED TO CHANGE MAGNET SWITCH FOR M-MOTOR, SLIDE ADJ, DRY EAS, VS-CONTROLLER, AUXILIARY RELAYS ETC.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
21-JULY		9	30	11	00	17	30	19	00	5.5			GEORGE
22-JUL		7	00	8	30	14	30	16	00	.5			GEORGE
27-JUL		7	00	8	20	18	00	19	00	8	.5		RHEY

SPARE PART	Qty	U/Price	Amount	Remark
				NOTE:
				1) LIGHT CURTAIN SENSOR FOR MACHINE NO. 1 & NO. 4 RECOMMEND FOR CHANGE.
				2) PRESS ACCURACY FOR MACHINE 1, 2, 3, 4 & - OK, BUT NO. 5 BOLSTER FLATNESS NG.
LABOUR CHARGES [NORMAL]	18.5	US$ 25	US$462.50	
[1½]	.5	US$ 37.50	US$18.75	
[2]				
TRANSPORT	3	US$ 25	US$75	
PACKING & DELIVERY CHARGE				
VAT				
TOTAL			US$556.25	

Authorised	Confirm	Incharge

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name RODERICK GAMBOA
Post SR ENGINEER
Sign
Date 07-27-16

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY