


Polaris Mold Fabrication Corp.
Lot 9-C FPIP PARK II -SEZ , STO. TOMAS, BATANGAS

| | |
|---|---|
| 客戶 Customer | Pricon Microelectronics,Inc |
| 聯絡人 Contact | Mr. Arnold Martinez |
| 電話 Tel | (63)2-843-0870 |
| 地址 Add | LISP I Cabuyao Laguna |
| 日期 Date | November 10, 2020 |

Control No. Q-PM-20-1020-125-00

## MOLD REPAIR QUOTATION

| | Part Name | Details | Process | Lead time | Material | Amount | Quantity | Total Price (USD) | Remarks |
|---|---|---|---|---|---|---|---|---|---|
| 1 | HF201P-03<br>B127416-001 | **TOP AREA FLASHES**<br>**Cav. A**<br>  | **Process**<br>1.)Welding<br>2.)Grinding Process<br>3.)Fabricate Electrode<br>4.)EDM Machining<br>5.)QC Inspection<br>6.)Polishing | 6 days | N/A | $300 | 3 loc. | $900 | |
| 2 | | **SIDE AREA FLASHES**<br>**Cav. A**<br>  | | | | $300 | 1 loc. | $300 | |
| 3 | | **TOP AREA FLASHES**<br>**Cav. B**<br>  | | | | $300 | 3 loc. | $900 | |
| | | | | | | | Total | **$2,100** | |

**Note:**

1. Zero Vat Rated
2. Delivery and pick-up : not included
3. Trial shot- not included.
4. Terms of payment: 30 days upon delivery

Thank you for your inquiry. We are looking forward of servicing your needs.

Prepared by: Erwin Alcantara

Noted by: _____

Approved by: Dennis Maligaya

Note : This will serve as advance order information while preparing P.O

Confirmed by: / Date: