NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0553

Customer: PRICON MICROELECTRONICS, INC. Date: 07 / 05 / 17

Model: NEX50TH-5EG M/C#:22A Mfg. yy/mm: 2016.03

Serial Number: H1051509GKI Gts.: 1619630

Controller: TACT IV

Reason for Maintenance

1) Machine can mold close even vacuum system is OFF.
   - Standard: machine can't mold close when vacuum system is OFF

Action Taken

1) Machine Inspection
   - Vaccum Pressure Switch not Functioning properly.
2) Change AV200 (Pressure/Vacuum Switch) From other machine. upon trial; machine OKAY.
3) Vacuum switch ~~(VG)~~. coil adjustment (From original switch) upon trial: machine OKAY

SERVICE BY:

1 B. Quiñones

2 N. Nishizawa

TIME:

Start	End
14 : 00	15 : 30

Total: 1.5 Hours

E. S. Molina 7/5/17
Authorized Signature

Service Fee: ₱ 4,000

Illustration

SQ No. _____ PO No. _____ SI No. _____ OR No. _____