MESCO, INC.
RELIANCE COR. BRIXTON STS., KAPITOLYO, PASIG CITY 1603
TELS.: 8631-1775 • FAX: (632) 8631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO Since 1956
QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR № 126590

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: LISP 1
MACHINE: VAI-II
SERIAL NO.: 10013A (10113A) CODE NO.:

SERVICEMAN: Raman / Ron
DATE: Feb 17, 2023
TIME START: 11:30
TIME FINISH: 2:00
TOTAL HRS.: TRAVELLING HOURS:

JOB COMPLETED: ☐ YES ☒ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☒ NO

REPORTED PROBLEM:

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training: X-axis error
☐ Installation ☐ Parts Measurement: APC alarm
☐ Shifting ☐ Others:

WORK DONE:

- Upon arival found out m/c not in use in operation
- APC alarm due to battery, customer to replace the type D battery
- Set up dial, checked x axis backlash found out different value at max 0.025mm
- checked Y-axis backlash — ok
- Test m/c backlash x-axis table moved by hand found max 0.06mm, decide to open the cover found out x-axis fill with coolant TO clogged drain
- clean the drain, found coolant trap level reaches the ballscrew
- found prob on ballscrew and bearing for x-axis
- open Y-axis to checked drain part — ok

☐ PARTS REPLACED ☒ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.
x-ballscrew	3884-T010-0200	1
deep groove bearing	6002DD-PC	1
bearing	NTN. 2A-BST17 x47	2
	- IBL x LP4/LS88	
lock nut	MRZ17	2

RECOMMENDATIONS:

For quotation x-axis ballscrew, bearing and lock nut

REMARKS:

PERSON IN CHARGE: N. MENDOZA
POSITION: SR. Engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY

CamScanner