FANUC PHILIPPINES CORPORATION

7th Floor, Glass Tower Unit C & D, 115 C. Palanca Jr. St.,
Legaspi Village, Makati City, Philippines
Tel. Nos. (632) 813-3155 to 56

Fax No. (632) 813-3157

F A N U C

FINAL QUOTATION

PRICON MIRCOELECTRONICS, INC.
No. 14 Ampere Street, Barangay Diezmo
Light Industry and Science Park 1 (LISP 1)
Cabuyao, Laguna
Tel. No. (02) 843-0864 to 70 / 049-549-3083
Fax No. (02) 889-5015 / **889-5274 / 889-6291**
Attn **Mr. Ollan Mendoza**
Cc
Email add: nolmend@pricon.ph

Quotation No.: **126060**

MR. No. : **G02194000**
SR No.: **12537**
Date : **December 19, 2017**

In compliance with your esteemed inquiry, we are pleased to quote you as follows:

Payment terms	***Net 30 Days.***
Specification	***As specified below.***
Remarks	***Prices are subject to change without prior notice. Zero-rated enterprise.***
	Quotation valid only within one week from the date hereof.
	Service rendered and part supplied for Ikegai Wado FPC-20VT Machine, S/N: 15A083.
	Please isse PO the soonest.

Thank you and await for your prompt and valuable order.

FANUC PHILIPPINES CORPORATION

HIROSHI SATO
MANAGING DIRECTOR

ITEM NO.	DESCRIPTION / SPECIFICATION	QTY. (Hrs/Pcs)	UNIT PRICE (Php)	AMOUNT (Php)
1	SERVICE FEE (Including travel time)			
	Basic charge (4hrs)			**12,500.00**
2	SVM			
	A06B-6096-H103 (Trade-in)	1		**98,000.00**
				110,500.00

NOTE
* NO CANCELLATION IS ALLOWED AFTER RECIEPT OF YOUR ORDER CONFIRMATION.
* PLEASE NOTE THAT FANUC PHILIPPINES CORPORATION WILL NOT BEAR ANY RESPONSIBILITY FOR PARTS REPLACED AND DAMAGED BY ANY PERSON OTHER THAN OUR SERVICE ENGINEERS.

"FANUC POLICY PROHIBITS THESE PRODUCTS FROM BEING USED FOR THE DEVELOPMENT, PRODUCTION, USE OR STOCKPILING OF WEAPONS OF MASS DESTRUCTION (NUCLEAR WEAPONS, BIOLOGICAL WEAPONS, CHEMICAL WEAPONS OR MISSILES)." FURTHER, RE-EXPORT TO ANOTHER COUNTRY MAY BE SUBJECT TO THE LICENSE OF THE COUNTRY FROM WHERE THE PRODUCT IS RE-EXPORTED".

Order Confirmation:

Signature over Printed Name

FANUC PHILIPPINES CORPORATION

FANUC

7th Floor, Glass Tower Unit C & D
115 C. Palanca Jr. St., Legaspi Village, Makati City 1229
Tel: (632) 813-3155/6 Fax: (632)- 813-3157

DRACON Microelectronics Inc
LISP ±

Service Report

MR No. G0 2194000
Date: 12-18-17

Date	12/19					
Leave Office	730	Hrs		Hrs		Hrs
Time in	1030					
Time out	1500					
Arrive Office						

Service Request by:	Ollan Mendoza	Service by	M. Rosales
CNC model	FS 21i MA	Serial No.	E0050523G
MTB	KEGAI WAD Model FPC-20VT	Serial No.	15A083 (CNC# 3)

Work Request

Z axis motor vibration

Phenomena, Cause, Step

Phenomenon. Problem occur during Z+ axis movement
Steps
1.) Check, no alarm on SVM
2.) Check current/load on Z axis during movement → ok
3.) Inspect mechanical → ok
4.) Replace SVM (A06B-6096-H103) with new SVM → ok
5.) Perform zero position for Z axis
6.) Try to move Z axis → ok
7.) Try to home position Z axis using different speed → ok
8.) Perform dry cutting → ok

Note: Machine is ready for set up
We will send quotation for back up battery.
Do not turn off the machine unless back up battery is replaced.

Used Parts

Item	Description	Specification No.	Q'ty
1	SVM	A06B-6096-H103 (Fanuc) (S/N: V01527934)	1

N. Mendoza
Customer's Signature
(Signature over Printed Name)

No. 12537