NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Sir VERGEL GARCIA

Q/S NO: QS 180125 003
DATE: January 25, 2018
SERVICE REPORT NO: A0858

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : February 25, 2018
Machine Model : PN40-SH MC#: 5A
Serial Number : P04Z010

DESCRIPTION	Q'TY	U/PRICE	TOTAL
*CAN NOT INJECT DURING AUTO OR SEMI-AUTO MODE	1	₱7,000	₱7,000 -
Action Taken			
*CHECKED THE PS2 (PRESSURE SWITCH 2)			
-INTERCHANGE PS2 FROM M/C# 15 TO M/C# 5A			
-SAME PROBLEM OCCURRED			
*CHECKED THE CHECK VALVE			
-INTERCHANGE CHECK VALVE FROM M/C#4			
-MACHINE TRIAL; OKAY | AUTOTEST;OKAY			
-FOUND OUT BROKEN CHECK VALVE			

TOTAL	₱7,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY: