NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Sir VERGEL GARCIA

Q/S NO: QS 170417 001
DATE: April 17, 2017
SERVICE REPORT NO: A0423

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : T/T Remittance 30days After INVOICE date
Validity : May 17, 2017
Machine Model : NEX50-5E MC#:
Serial Number : H00511098K1

DESCRIPTION	Q'TY	U/PRICE	TOTAL
*MACHINE ALARM WITH:	1	₱4,000	₱4,000 -
-55457:EJECTOR AXIS AMP. CONTROL VOLTAGE ABNORMAL			
-55157:INJ AXIS AMP. CONTROL VOLTAGE ABNORMAL			
-55257:MTG AXIS AMP CONTROL VOLTAGE ABNORMAL			
-55357:CLAMP AXIS AMP. CONTROL VOLTAGE ABNORMAL			
-54103:INJ AXIS ENCODER ERROR			
-5515F:INJ AXIS DRIVER ERROR (SERVOPROCESSOR/MEMORY/CPU)			
-5525F:MTG AXIS DRIVER ERROR (SERVOPROCESSOR/MEMORY/CPU)			
-54303:CLAMP AXIS ENCODER ERROR			
-5535F:CLAMP AXIS DRIVER ERROR			
-5F201:INVERTER 1 COMMUNICATION NO RESPONSE			
-54403: EJECTOR AXIS ENCODER ERROR			
Action Taken			
*FOUND SHORT CIRCUIT ON NFB29 (NO FUSE BREAKER):W/ OUTPUT			
CONNECTION OF 220VAC			
*REMOVE WIRINGS (NO ATTACHMENT ON CONTROL PANEL)			
*ARRANGED WIRINGS HARNESS FOR OVERDRIVE CONNECTION (24VDC)			
*POWER ON/TEST RUN/CONFIRMATION			
*ALL MACHINE MOVEMENTS ARE FUNCTIONAL			

TOTAL	₱4,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

B. Quiñones

Prepared By: