NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Mr RED

Q/S NO: QS 171207 001
DATE: December 7, 2017
SERVICE REPORT NO: A0778

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : January 7, 2018
Machine Model : PN60-5AN MC#: 21A
Serial Number : E00610001K1

DESCRIPTION	Q'TY	U/PRICE	TOTAL
***SCREW FORWARD/BACKWARD OF MACHINE, NOT FUNCTIONING**	1	₱24,000	₱24,000 -
Action Taken			
***SERVO VALVE BROKEN**			
-REPLACED WITH NEW SERVO VALVE			
*AFTER REPLACING SERVO VALVE, SCREW FORWARD IS FUNCTIONING			
EXCEPT SCREW BACKWARD BECAUSE OF DAMAGED INJECTION RAM			
PACKINGS			
-REPLACED INJECTION RAM PACKING SET			
-MACHINE OKAY			
-INSTALLED NEW PROGRAM FOR SERVO VALVE TODAY			
(THIS MACHINE WAS THRICE VISITED FOR TROUBLESHOOTING)			

TOTAL	₱24,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY: