NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Ms Rebecca D. Valenzuela

Q/S NO: QS 180316 001
DATE: March 16, 2018
SERVICE REPORT NO: A0895

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : April 16, 2018
Machine Model : FE80S12H MC#: 16
Serial Number : P08Q011

DESCRIPTION	Q'TY	U/PRICE	TOTAL
*NO EJECTOR BACKWARD (MANUAL TEST)	1	₱4,000	₱4,000 -
Action Taken			
*CHECK THE DIAGNOS FOR INPUT & OUTPUT			
-NO INPUT			
*CHECK THE CAM SWITCH			
-FOUND OUT THAT ONE WIRE FOR COMMON CONNECTION WAS			
DISCONNECTED			
*INSTALLED THE WORE PROPERLY			
*MANUAL TEST;OK / AUTOTEST; OK			

TOTAL	₱4,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY:



NPPIS007