NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Ms Rebecca Valenzuela

Q/S NO: QS 180417 001
DATE: April 17, 2018
SERVICE REPORT NO: A0971

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : May 17, 2018
Machine Model : PN60-5AN MC#: 12A
Serial Number : E0061500K1

DESCRIPTION	Q'TY	U/PRICE	TOTAL
SERVICE FEE FOR:	1	₱7,000	₱7,000 -
*MATERIAL LEAK AT NOZZLE TIP			
Action Taken			
*CHECKED THE CONDITION OF NOZZLE TIP			
-FOUND OUT THAT NOZZLE TIP HAVE DENT AND ALREADY DAMAGED			
*TRIED TO CONDUCT NOZZLE CENTERING			
-MATERIAL LEAK AT NOZZLE TIP NOT RESOLVED			
*REPLACED NOZZLE TIP WITH OLD NOZZLE TIP FROM CUSTOMER			
-RESULT: NO MATERIAL LEAK ON NOZZLE TIP AFTER REPLACEMENT			

TOTAL	₱7,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY: