NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Ms Rebecca Valenzuela

Q/S NO: QS 180515 001
DATE: May 15, 2018
SERVICE REPORT NO: A0996

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : June 15, 2018
Machine Model : PN40-5H MC#: 5A
Serial Number : P04Z010

DESCRIPTION	Q'TY	U/PRICE	TOTAL
SERVICE CHARGE FOR TROUBLESHOOTING PROBLEM:	1	₱20,000	₱20,000 -
*NO CONTROL OF SCREW SPEED			
*LOW PRESSURE OF INJECTION UNIT			
*SCREW FORWARD NOT FUNCTIONING			

TOTAL	₱20,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY: