FANUC PHILIPPINES CORPORATION

Unit 1 Orient Goldcrest Bldg. 10 Lot4, Block 1, Phase 7A, Laguna Technopark Inc.
Tel. Nos.049-546-0178/79
Fax No.049-546-0180

FANUC

Quotation

PRICON MICROELECTRONICS, INC.
No.14 Ampere St. Brgy. Diezmo
Light Industry and Science Park 1, Cabuyao, Laguna
Tel No.: 843-0864 to 70/ (049) 544-9221
Fax No.: 889-5015 / 889-5274

Attn : Ms. Lemacorp Sarmiento (lasarmiento@pricon.ph)
Mr. Ricardo Martin III (rcmartin@pricon.ph)

Ref No : QT0004013-00
Date : Apr 07, 2021
MR NO.: G03031000

In compliance with your esteemed inquiry, we are pleased to quote you as follows:

Payment Terms : Net 30 Days
Specification : As specified below.
Remarks : Prices are Subject to change without Prior Notice.
: Quotation valid only within one week from the date hereof.
: Please issue PO the soonest.

Thank you and await for your prompt and valuable order.

LUIS M. LAGUIDAO JR.
SERVICE MANAGER

ITEM NO.	DESCRIPTION/SPECIFICATION No.	QTY (Pc/s)	UNIT PRICE (PHP)	AMOUNT (PHP)
1	Hourly Charge RENDERED FOR ROBOSHOT S50IA S/N: A191P0010	2	2,000.00	4,000.00

Confirm :

FANUC POLICY PROHIBITS THESE PRODUCTS FROM BEING USED FOR THE DEVELOPMENT, PRODUCTION, USE OR STOCKPILING OF WEAPONS OF MASS DESTRUCTION (NUCLEAR WEAPONS, BIOLOGICAL WEAPONS, CHEMICAL WEAPONS OR MISSILES).FURTHER, RE-EXPORT TO ANOTHER COUNTRY MAY BE SUBJECT TO THE LICENSE OF THE COUNTRY FROM WHERE THE PRODUCT IS RE-EXPORTED.

Maintenance Report

FANUC

MR No.

G03031000

FANUC PHILIPPINES
CORPORATION
Unit 1 Orient Goldcrest Bldg. 10,
Lot 4. Block 1, Phase 7A,
Laguna Technopark Inc., Biñan,
Laguna
TEL:49-546-0178 or 0179
FAX:49-546-0180

Customer□Pricon Microelectronics, Inc.

(1245) Tel. 843-0864 to 70/ (049) 544-9221 Tax No.

Address□No. 14 Ampere St., Light Industry & Science Park 1,
Brgy. Diezmo,
Cabuyao, Laguna

Requested by□Mr. Lemacorp Sarmiento

Agent□Pricon Microelectronics, Inc.

Date□ 2021/04/06

Seiban□CQ02018 Customer Req□2021/04/05 16:00 Customer Exp□2021/04/06 11:00

Quotation No.□ QT0014013-00 Order No□ Order Date□

Install Date□2019/02/28 Job Type□New

MTB Name□FANUC CORPORATION

M/C Model□FRSHOT A-S50IA M/C SN□A191P0010

CNC Model□FRSHOT A-S50IA CNC SN□A191P0010

Laser Model□ Laser SN□ RUN HOUR□

CNC Alarm□ SVM Alarm□ SPM Alarm□

PSM Alarm□ Other Alarms□

Date	Departure	Job Start	Job End	Travel	Break	Job
2021/04/06	12:00	13:00	14:00	1 hours	0 hours	1 hours

Condition And Result	Adjustment

Phenomena□ Graph on server process monitor is not updated

Cause□ Communication is properly established

Treatment□ 1.) Check ROBOSHOT Linki server ---> Server can perform ROBOSHOT Viewer properly
2.) Run Data Control ---> OK, graph was updated
3.) Deleted old server back up ---> OK

Note: Teach customer how to run DATA CONTROL and delete old server files

Description		
1. Service Hours	(Basic Charge)	
	(Hour Charge)	Hours
2. Travel Hours		Hours

No.	Parts Description	Specification	Edition/SN	Trade In	QTY

C/O Ricardo Martin III

L. Sarmiento

Customer's Signature

Service by

Engr. Michael M. Rosales