FANUC PHILIPPINES CORPORATION (PEZA REGISTERED)

FANUC

Unit 1 Orient Goldcrest Bldg. 10 Lot4, Block 1, Phase 7A, Laguna Technopark Inc.
Tel. Nos.049-546-0178/79
Fax No.049-546-0180

Quotation

PRICON MICROELECTRONICS, INC.
No.14 Ampere St. Brgy. Diezmo
Light Industry and Science Park 1, Cabuyao, Laguna
Tel No.: 843-0864 to 70/ (049) 544-9221
Fax No.: 889-5015 / 889-5274

Ref No : QT0009100-00
Date : Jan 20, 2023
MR No G03633300

Attn : Ms. Anna Marie Nueva (amnueva@pricon.ph)
Ms. Rebecca Valenzuela (rdvalenzuela@pricon.ph)

In compliance with your esteemed inquiry, we are pleased to quote you as follows:

Payment Terms : **Net 30 Days after Invoice Date**
Specification : As specified below.
Remarks : Prices are Subject to change without Prior Notice.
Quotation valid only within one month from the date hereof.
Please issue PO the soonest.

Thank you and await for your prompt and valuable order.

HISAO SATO
MANAGING DIRECTOR

ITEM NO.	DESCRIPTION/SPECIFICATION No.	QTY (Hrs/Pcs)	UNIT PRICE (PHP)	AMOUNT (PHP)
1	A40L-8001-0049#W40ALCA NOZZLE HTR SHORT	1	4,900.00	4,900.00
2	Hourly Charge (Including travel time) RENDERED FOR FRS S100IA S/N: A191S0112	5	2,000.00	10,000.00
	TOTAL			**14,900.00**

Confirm :

FANUC POLICY PROHIBITS THESE PRODUCTS FROM BEING USED FOR THE DEVELOPMENT, PRODUCTION, USE OR STOCKPILING OF WEAPONS OF MASS DESTRUCTION (NUCLEAR WEAPONS, BIOLOGICAL WEAPONS, CHEMICAL WEAPONS OR MISSILES).FURTHER, RE-EXPORT TO ANOTHER COUNTRY MAY BE SUBJECT TO THE LICENSE OF THE COUNTRY FROM WHERE THE PRODUCT IS RE-EXPORTED.

Maintenance Report

FANUC

MR No.

G03633300

Customer Pricon Microelectronics, Inc.

(1245) Tel. 843-0864 to 70/ (049) 544-9221 Tax No.

Address No. 14 Ampere St., Light Industry & Science Park 1,
Brgy. Diezmo,
Cabuyao, Laguna

FANUC PHILIPPINES
CORPORATION
Unit 1 Orient Goldcrest Bldg. 10,
Lot 4. Block 1, Phase 7A,
Laguna Technopark Inc., Biñan,
Laguna
TEL:49-546-0178 or 0179
FAX:49-546-0180

Requested by
Ms. Rebecca Valenzuela

Agent Pricon Microelectronics, Inc.

Date 2023/01/17

Seiban CQ03754 Customer Req 2023/01/17 09:00 Customer Exp 2023/01/17 09:00

Quotation No. Order No Order Date

Install Date 2019/02/28 Job Type New

MTB Name FANUC CORPORATION

M/C Model FRSHOT A-S100IA M/C SN A191S0112

CNC Model FRSHOT A-S100IA CNC SN A191S0112

Laser Model Laser SN RUN HOUR

CNC Alarm SVM Alarm SPM Alarm

PSM Alarm Other Alarms

Date	Departure	Job Start	Job End	Travel	Break	Job
2023/01/17	12:30	13:30	17:30	1 hours	0 hours	4 hours
Condition And Result		Replace Parts				

Phenomena BARREL HEATER DOESNT WORK

Cause DEFECTIVE NOZZLE HEATER

Treatment 1. CHECK MACHINE CONDITION --> AT POWER ON BARREL HEATER DOESNT WORKS, FOUND OUT CIRCUIT BREAKER HAVE TRIP OFF
2. CHECK FUSE IN USER PCB AND OTHER PCB --> OK, ALL FUSE ARE OK
3. TRIED TO ON CIRCUIT BREAKER THEN POWER ON, THEN ON TEMPERATURE --> AFTER SOMETIME CIRCUIT BREAKER TRIPS
4. TRIED TO REPLACE THERMOCOUPLE PCB --> STILL THE SAME, BREAKER TRIPS AFTER A COUPLE OF MINUTES
5. REPLACE NOZZLE HEATER --> OK, MACHINE DOESNT TRIPS ANYMORE

Description		
1. Service Hours	(Basic Charge)	
	(Hour Charge)	Hours
2. Travel Hours		Hours

No.	Parts Description	Specification	Edition/SN	Trade In	QTY
1	NOZZLE HTR SHORT	A40L-8001-0049#W40ALCA		No	1

MR J. ABHAN

JAP / ACB

Customer's Signature

Service by
Engr. John Aris Bathan