NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4567

DATE JUNE 11, 2018

SERVICE REPORT

CUSTOMER'S NAME PRICON MICRO ELECTRONICS INC.	CUST. SIGNATURE
ADDRESS LISP I NO 14 AMPERE ST LISP I BRGY DIEZMO CABUYAO LAGUNA	
SERVICE BY MELVIN D. MORCILLA	SERVICE MAN SIGN

1) REPAIR	2) EXAMINATION	3) OVERHAUL	4) FITTING	5) SUPERVISION OF START UP
☑	☐	☐	☐	☐

ACTION TAKEN EXG-150 SN-003359 . EXG-150 SN-T-003404
- REPAIR OF HENDY PENDANT EMERGENCY STOP. REPAIR OF ON OFF SWITCH PUT TO CUT CONNECTION.

REMARKS: UNITS ARE NOW READY FOR RUN.

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				
				LABOR AMOUNT	₱ 4,000

TIME STARTED	TIME FINISHED	TOTAL TIME	TRAVEL TIME
8:15	11:00	2 HRS	

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 13-Jun-18

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2018-06-005-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao, Laguna

ATTENTION **Ms. Rebecca Valenzuela**

Dear Ms. Rebecca Valenzuela
We are honored to offer our services as follows for the following:

Machine Model Serial No

Brief Description of the Trouble or the Work to be done

EXG-150 SN: 003359 EXG-150 SN: T-003404
Repair of handy pendant emergency stop. Repair of on off switch due to cut connection.
Remarks: Units are now ready for run.

Special Instructions

Service Report No. 4567 dated June 11, 2018.

Machine Type	Working Task	Fee/task	Task	Line Total
	SERVICE FEE	4,000.00 P/task	1 task	4,000.00 P
			Total	4,000.00 P

Respectfully Yours

Jon Diaz