NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY, 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 5030

SERVICE REPORT

DATE July 10, 2021

CUSTOMER'S NAME PRICON

ADDRESS #14 AMPERE ST. LNPI Cabuyao Laguna

CUST. SIGNATURE VINCENT ENGENIA

SERVICE BY Frocklie, Celai & Dondon.

SERVICE MAN SIGN

1) REPAIR ☐	2) EXAMINATION ☐	3) OVERHAUL ☐	4) FITTING ☐	5) SUPERVISION OF START UP ☐

ACTION TAKEN PN60-5AN S# E0061000IKI; No movement for screw FW/BW. Carbonized material stuck at the barrel. (7-9-21) Removals of screw and barrel, to be decarbonized. (7-10-21)

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1		SERVICE FEE			₱28,400.00
2					
3					
4					
5					
	LABOR CHARGE				

TIME STARTED	TIME FINISHED	TOTAL TIME	TRAVEL TIME	LABOR AMOUNT	₱ 28,400.00

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 13-Jul-2021

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2021-07-002-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao,

ATTENTION **Ms. Rebecca Valenzuela**

Dear Ms. Rebecca Valenzuela
We are honored to offer our services as follows for the following:

Machine Model PN60-5AN Serial No E00610001K1

Brief Description of the Trouble or the Work to be done

July 9 - No movement for screw FW/BWD. Carbonized material stucked at the barrel.
July 10 - Removal of screw and barrel to be decarbonized.

Special Instructions

Service Report No. 5030 dated July 10, 2021

Machine Type	Working Task	Fee/task	Task	Line Total
PN60-5AN	Service Fee	28,400.00 P/task	1 task	28,400.00 P
			Total	28,400.00 P

Respectfully Yours

Natasha Valiente