② ご請求明細

No. 1-26683

サービス作業報告書

2018 年 12 月 07 日

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 RONALD M. SOLARES ㊞

作業区分	1 出張作業	2 出張納品	3 社内作業
有無区分	1 受注	2 有償	3 無償

指図書No・対策No

訪問先会社名 (コードNo) PRICON MICROELECTRONICS INC. 殿

所属部署

御担当者 MR. RONALD SOLARES 様

出張区域 都道府県 PHILIPPINES 市 CABUYAO 郡市区町 LAGUNA

請求先会社名 (コードNo) 殿

所属部署

御担当者 様

コードNo	作業担当	営業担当
00124	LIBRADILLA, R.	YAMAMITA

機種	製造番号	製造年月日
6 HOP FINE 450X-GIIB	42055 79004	年 月 日

作業内容 再訪問 機種区分 機種

CHECKING / FIXING

不具合詳細

NO MOLD OPEN LIMIT SIGNAL
BOTH ROBOT SIDE ENTRY AND SWING TYPE ROBOT

初回発生日 / / コントローラーエラーNo サーボアンプエラーNo

原因

処置

FIXING WIRING OF INTERLOCK AND
REWIRING SIGNAL OF MOLD OPEN LIMIT TO INJECTION MACHINE
TRIAL CHECK-OK, ONE CYCLE CHECK-OK

結果 WORK FINISHED

経過判定

見積りNo 無償理由

MEMO

NOTE: WIRING OF USHIO CAMERA MUST USE RELAY
NOW IN DIRECT CONNECTION

使用部品内訳 払出部門 001980

受払	No.	部品コードNo	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						

売上日 / 納品書No D% 合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	US $40
作業料金	US $82.5
小計	
消費税	
合計金額	US $122.5

作業開始時間	19 時 00 分
作業終了時間	15 時 30 分
作業外時間	▲ - 時間 - 分
作業時間	1 時間 30 分

通知No.	
指図No.	
受注No.	

YUSHIN 株式会社ユーシン精機

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Pricon Micro Electronics INC

Date: December 10, 2018

Attn: Mr. Ronald Solasco

YPEP-QSC-181210-01A

Quotation

Subject: Parts for Yushin Take-out Robot

1	Amount	: USD $ 123
2	Time of Delivery	: Work Already Done (12-07-18)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation	1 lot	$ 123	$ 123
2		Checking/ Fixing			
	Total :		1 lot		$ 123

Note :

a. Any other specification which is not described in the above to be extra.
b. **For HOP FIVE 450X-GIIB Sn: 4205579004**
c. Service Report No.1-26683

Yushin Precision Equipment Co., Ltd.

Rosalie Rañola

for T. INANO
General Manager, Southern Asia Sales Department