② ご請求明細

サービス作業報告書

No. 1-26977

2020年 12 月 14 日

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 ALJHON D ANONUEVO ㊞

作業区分	1 出張作業	2 出張納品	3 社内作業	指図書No.・対策No.
	(1)			
有無区分	1 受注	(2) 有償	3 無償	
		(2)		

訪問先会社名 (コードNo.)	所属部署		出張区域	PHILIPPINES 都道府県 CABUYAO 市 LAGUNA 都市区町	
PRICON MICROELECTRONICS INC 殿	御担当者	ALJHON ANONUEVA 様			
請求先会社名 (コードNo.)	所属部署		コードNo.	作業担当	営業担当
Ditto 殿	御担当者	様	001124	R. LIZBRADILLA A. ESCUBIN B. PANGANIBAN	K. YAMASHITA

機種	製造番号	製造年月日
11-HOP 550 RX	3409845001	2007年09月07日

作業内容	再訪問	機種区分	機種	ROBOT REPAIR	
不具合詳細					
初回発生日 / /	コントローラーエラーNo.		サーボアンプエラーNo.		
原因					
処置	- TRANSFER ARM CYLINDER FROM MC V01 TO MC V01 - I/O SIGIVAL CHECK - OK, ONE CYCLE CHECK - OK, TRIAL CHECK - OK				
結果	FINISH				
経過判定					
見積りNo.	無償理由				

MEMO: NOTE: NEED TO QUOTE ARM CYLINER AND PACKING FOR ARM CYLINDER

使用部品内訳　払出部門 001980

受払	No.	部品コードNo.	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						

売上日 /	納品書No.	D%	合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	USD $40
作業料金	USD $165
小計	
消費税	
合計金額	USD $205

作業開始時間	16 時 00 分
作業終了時間	19 時 00 分
作業外時間	▲ - 時間 - - 分
作業時間	3 時間 00 分

Emailed
DEC 15 2020

			アリセ 20.12.15	通知No.	
				指図No.	
				受注No.	

YUSHIN 株式会社ユーシン精機

YUSHIN

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Pricon Micro Electronics Inc.
Attn:Mr. Aljhon Anonuevo

Date:December 15,2020

YPEP-QSC-201215-03A

Quotation

Subject: Parts for Yushin Take-out Robot

1	Amount	USD $ 205
2	Time of Delivery	Work already done (2020.12.14)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation Robot Repair	1 lot	$ 205	$ 205
	Total :		1 lot		$ 205

Note :

a. Any other specification which is not described in the above to be extra.
b. **For V-HOP 550RX SN.3409845001 Mfg.2007.09.07**
c. Service Report No.1-26977

Yushin Precision Equipment Co., Ltd.

Rosalie Rañola

for T. INANO
General Manager, Southern Asia Sales Department