② ご請求明細

No. 1-26534

サービス作業報告書

2019 年 01 月 03 日

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 [signature] 印

作業区分	1 出張作業	2 出張納品	3 社内作業
有無区分	1 受注	2 有償	3 無償

指図書No.・対策No. ~

訪問先会社名	(コードNo.)	所属部署	
PRICON MICROELECTRONICS INC. 殿		御担当者	RAFFY ANDAYA 様
請求先会社名	(コードNo.)	所属部署	
Ditto 殿		御担当者	Mr. Imano 様

出張区域: PHILIPPINES 都道府県 CABUYAO 市 LAGUNA 郡市区町

コードNo.	作業担当	営業担当
001214	D. DE LEON H. ESCOBIN	K. YAMASHITA

機種	製造番号	製造年月日
HOPFive 450X - GIIB	4205579004	2015 年 02 月 19 日

作業内容: 再訪問 / 機種区分 / 機種

TROUBLESHOOTING / CHECKING

不具合詳細: NO MOLD OPEN LIMIT SIGNAL

初回発生日 / / コントローラーエラーNo. サーボアンプエラーNo.

原因: MACHINE NO OUTPUT FOR Y3C SIGNAL (NISSEI NEX 15 III)

処置: CHECKING WIRINGS, SIGNALS, SUPPLY. FOUND OUT THAT THE MACHINE HAS VERY LOW SIGNAL OUTPUT (1.3V) THAT SHOULD BE IN (24V) FOR Y3C SIGNAL.

結果: FINISHED

経過判定

見積りNo. 無償理由

MEMO

使用部品内訳 払出部門 001980

受払	No.	部品コードNo.	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						

売上日 / 納品書No. D% 合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	US $ 40
作業料金	US $ 55
小計	
消費税	
合計金額	US $ 95

Emailed JAN 04 2019

作業開始時間	16 時 00 分
作業終了時間	17 時 00 分
作業外時間	▲ - 時間 - 分
作業時間	1 時間 00 分

通知No.	
指図No.	
受注No.	

19.1.04

YUSHIN 株式会社ユーシン精機

YUSHIN PRECISION EQUIPMENT CO., LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL. +81-75-933-9555 FAX. +81-75-933-9590

Pricon Micro Electronics Inc.

Date: January 04,2019

Attn: Mr. Ronald Solasco

YPEP-QSC-190104-01A

Quotation

Subject: Parts for Yushin Take-out Robot

1	Amount	: USD $ 95
2	Time of Delivery	: Work Already Done (01-03-19)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation	1 lot	$ 95	$ 95
2		Checking/ Fixing			
	Total :		1 lot		$ 95

Note :

a. Any other specification which is not described in the above to be extra.
b. **For HOP FIVE 450X-GIIB Sn: 4205579004 Mfg.2015.02.19**
c. Service Report No.1-26534

Yushin Precision Equipment Co., Ltd.

Rosalio Rañola

for T. INANO
General Manager, Southern Asia Sales Department