# Sodick

**SODICK PHILIPPINES INC**
**Company Regn : CS201501353**
**Company Tin : 008-944-890**
M201 Unit,GRM Bldg.,124 East Science Ave.,cor Trade Ave.,
Laguna Technopark, Binan City, Laguna 4024
TEL#: (049) 544 0936

**№ 001587**

2005-07

## SERVICE REPORT

| | | | |
|---|---|---|---|
| CUSTOMER : PRICON | | MACHINE : TR55EH2 | S/N T0G1 |
| PERSON IN CHARGE : | | CONTROLLER : TRD-5 | S/N |
| COUNTRY : PHILIPPINES | | SOFTWARE VER. : | |
| INSTALLATION DATE: | | OPTION : AWT.ATC. OTHERS : | |

| SERVICE DATE | STARTING TIME | FINISHING TIME | TOTAL TIME | ENGINEER |
|---|---|---|---|---|
| 01/07/18 | 1300H | 1630H | 2 HR 30 MIN | AVEL, DEE |
| | | | HR MIN | |
| | | | HR MIN | |

**MATTER OF REQUEST / NATURE OF PROBLEM**

SD: 18
PD: 22

- REPLACEMENT OF PISTON PUMP.
- SERVO DRIVER FOR MOLD CLOSE.

**DESCRIPTION OF SERVICE**

* INSTALLED NEW PISTON PUMP.
* RECONNECT PIPING AND WIRING CONNECTION.
* CHECKED MOTOR ROTATION (OK)
* CALIBRATED TULINE PRESSURE (OK)
* TEST FUNCTION (OK)

| | | | |
|---|---|---|---|
| ☐ WARRANTY | ☒ SERVICE CHARGE | ☒ COMPLETED | ☐ MONITORING |
| ☐ F.O.C | ☐ SERVICE CONTRACT | ☐ NOT COMPLETE | RE-ARRANGE DATE: |

| PARTS CODE | DESCRIPTION | QTY | PARTS CODE | DESCRIPTION | QTY |
|---|---|---|---|---|---|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

**SODICK PHILIPPINES, INC.**

A. CABUSPANG
*Engineer*

V. GARCIA
*Signature / Company's Stamp*

Service's Copy