SODICK PHILIPPINES INC
Company Regn : CS201501353
Company Tin : 008-944-890
M201 Unit,GRM Bldg.,124 East Science Ave.,cor Trade Ave.,
Laguna Technopark, Binan City, Laguna 4024
TEL#: (049) 544 0936

№ 002360

SERVICE REPORT

CUSTOMER : PRICON		MACHINE : TR40EHV	S/N 5288
PERSON IN CHARGE :		CONTROLLER : TRD 6	S/N
COUNTRY : PHIL		SOFTWARE VER. :	
INSTALLATION DATE		OPTION : AWT.ATC. OTHERS :	

SERVICE DATE	STARTING TIME	FINISHING TIME	TOTAL TIME	ENGINEER
July 27,2020	1300	1430	1 HR 30 MIN	Avel / Mond
			HR MIN	
			HR MIN	

MATTER OF REQUEST / NATURE OF PROBLEM

Mold overtemperature

SD : 22
PD : 22
Total shot: 330115

DESCRIPTION OF SERVICE

- Check SSR D1, D2, D3 and D4
- Found out D1 SSR always have contact
- Replace D1 SSR and fix cable connection
- Check function (ok)
- Mold temperature Stable

☐ WARRANTY	☑ SERVICE CHARGE	☑ COMPLETED	☐ MONITORING
☐ F.O.C	☐ SERVICE CONTRACT	☐ NOT COMPLETE	RE-ARRANGE DATE:

PARTS CODE	DESCRIPTION	QTY	PARTS CODE	DESCRIPTION	QTY

SODICK PHILIPPINES, INC.

R. Molano
Engineer

A.P. Martin
Signature / Company's Stamp

Service's Copy