NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0134

Customer: PRICON MICROELECTRONICS INC. **Date:** 05 / 16 / 2017

Model: FE80S12H **Mfg. yy/mm:** 1095, 9

Serial Number: P08P009 **Gts.:**

Controller: N93C

Reason for Maintenance

- NO MOVEMENT OF SCREW FWD AND BACKWARD

Action Taken

- CHECKING OF VALVE 241 & 240
- FOUND OUT ~~THAT~~ 241 WAS NOT CONNECTED - 240 HAVE FOREIGN MATERIAL INSIDE
- INSTALL 241 VALVE TOGETHER WITH 240 VALVE
- MACHINE OKAY

SERVICE BY:

1 R. RAMON / N. NISHIZAWA

2 X. RAMIREZ

TIME:

Start	End
15 : 30	17 : 30

Total: 2 Hours

Authorized Signature

Service Fee: ₱ 10,000.00

Illustration

NOTE:
- AFTER TROUBLE SHOOTING OF MACHINE PLEASE RETURN THE ORIGINAL POSITION OF PARTS.

THANK YOU

SQ No. _____ PO No. _____ SI No. _____ OR No. _____