NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0971

Customer: PRICON MICROELETRONICS Inc. **Date:** 04 / 16 / 2018

Model: PNGO-SAN **Mfg. yy/mm:** 2016.03

Serial Number: E00615004K1 m/c #: 12A **Gts.:** 21386038

Controller: TACT

Reason for Maintenance

➤ NOZZLE LEAK

Action Taken

➤ CHECK THE CONDITION OF NOZZLE TIP
– FOUND OUT THAT NOZZLE TIP HAVE DENT & ALREADY DAMAGE
➤ TRY TO CONDUCT NOZZLE CENTERING
– BUT STILL NOZZLE LEAK
➤ DECIDE TO REPLACE ANOTHER NOZZLE (OLD NOZZLE)
– RESULT OKAY

SERVICE BY:

1 R. BATTAD

2 _____

TIME:

Start	End
14 : 00	18 : 00

Total: 4 Hours

EBaul 4/16
Authorized Signature

Service Fee: ₱ 7,000.00

Illustration

FOR QUOTATION OF NOZZLE

SQ No. _____ PO No. _____ SI No. _____ OR No. _____

(2) Agent