# NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

## SERVICE REPORT

No.: A 2440

Customer: PRICON MICRO ELECTRONICS INC. Date: 01 / 06 / 20

Model: FE 80S12H Machine no. 15 Mfg. yy/mm: 1995 . 8

Serial Number: P08 P009 Gts.: 2217186

Controller: N93C M/C Service Requested By: SIR HENRY

**Reason for Service / Machine Problem**

INSTALLATION OF NEW RUBBER BUSH

**Action Taken**

> INSTALL NEW RUBBER BUSH
> CUSTOMER INSTALL NITROGEN
FOR CONTINUATION OF REFILLING OF NITROGEN, DUE TO ~~SHORT~~ FEW STOCK
> REACH ONLY 70 MPA
> NISSEI RECOMMEND ATLEAST 110 MPA BEFORE DRY RUN
>

**SERVICE BY:**

1 X. RAMIREZ 3

2 F. CHING 4

Henry [illegible]
Authorized Customer Name & Signature

**TIME:**

| Start | End |
|---|---|
| 14 : 00 | 15 : 30 |

Total: 1 hrs. 30 mins.

Service Fee: Php n/a

*Recommendation/Parts for Quotation*

* NOTE:
SERVICE FEE TO FOLLOW AFTER COMPLETION OF MACHINE SERVICE / TROUBLESHOOTING