NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2445

Customer: PRICON MICRO ELECTRONICS INC. Date: 01 / 16 / 20

Model: FE80S12H Machine no. 15 Mfg. yy/mm: 1995. 9

Serial Number: P08 P009 Gts.: 2 217186

Controller: N93C M/C Service Requested By: SIR LEANDER

Reason for Service / Machine Problem

CONTINUATION INSTALLING OF NITROGEN

Action Taken

> INSTALL NITROGEN NOW REACH 110 kgF/cm² - OKAY
>CHANGE HYDRAULIC HOSE (FROM OIL MOTOR TO ACC. FILTER) DUE TO OIL LEAK
>REFILL HYDRAULIC OIL #46 UP TO MAX. LEVEL
>POWER ON / HEATER ON / MOTOR ON
>CHECKED ACC PRESSURE (@ MOTOR ON MODE) 140-150 kgf/cm²
>MACHINE TEST RUN (W/ PRODUCT) : OK
>MACHINE CAN BE USE BY CUSTOMER

SERVICE BY:

1 X. RAMIREZ 3 N. NISHIZAWA

2 F. CHING 4

Authorized Customer Name & Signature

TIME:

Start	End
10 : 00	14 : 00

Total: 3 hrs. 30 mins.

Service Fee: Php 24,000.00

Recommendation/Parts for Quotation

* TOTAL SERVICE FEE FROM START OF SERVICE WITH SERVICE REPORT NO. 2440

TOTAL OF 5HRS (2 DAYS SERVICE)