NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2573

Customer: PRICON MICROELECTRONICS INC. Date: 06 / 23 / 20

Model: FE80S12H Machine no. 16 Mfg. yy/mm: 1995. 9

Serial Number: P08Q011 Gts.: 3397192

Controller: N93C M/C Service Requested By: SIR ALJOHN

Reason for Service / Machine Problem

MACHINE EJECTOR CANNOT BACKWARD

Action Taken

> CHECKED VOLTAGE OF SELECTOR SWITCH FOR EJECTOR FORWARD HAVE BUT BACKWARD NO HAVE
> CHECKED ALSO AT DIAGNOS MONITOR HAVE INPUT BUT NO HAVE OUT PUT
> TRY TO CONNECT THE EJECTOR BLUD TO "132" HAVE VOLTAGE BUT STILL CANNOT BACKWARD
> TRY TO CHANGED TERMINAL BUT SAME PROBLEM BARROW FROM OTHER MACHINE
> TRACE THE CONNECTION OF THE WIRE THAT HAVE NO VOLTAGE FOUND OUT "134" THE WIRE HAVE CUT, FIXED THE WIRE
> TRY TO CONNECT AND CHECKED THE VOLTAGE NOW HAVE 24V
> CONDUCT FUNCTION OF EJECTOR NOW OKAY CAN BACKWARD

SERVICE BY:

1 R. PANTON 3

2 F. CHING 4

TIME:

Start	End
09 : 30	13 : 00

Total: 3 hrs. 30 mins.

ALJHN B. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php 7,000.00

Recommendation/Parts for Quotation