NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2618

Customer: PRICON MICROELECTRONICS **Date:** 11 / 17 / 20

Model: NEX50-5E **Machine no.** 3A **Mfg. yy/mm:** 2012.01

Serial Number: H0051109SK1 **Gts.:** 6928415

Controller: TACT **M/C Service Requested By:** SIR ALJHON

Reason for Service / Machine Problem

"MACHINE CHECKING DUE TO UNUSUAL SOUND DURING SCREW ROTATION/BACKWARD MOVEMENT"
[CAME: ON MANUAL METERING, REACHED TO SCREW RTN PROTECT TRQ LIMIT]

Action Taken

> CHECKED METERING BELT & PULLEY CONDITION; STILL OK
> RETIGHTENED & CHECK BOLTS FOR SERVO MOTOR, SCREW COUPLING; ALL BOLTS NO PROBLEM, NO LOOSENED DURING ROTATION (AUTO-CUSHION)
> CONDUCT INJECTION ZERO RESET FOR RESIN PRESSURE (ACTUAL is -11kgf/c)
> CONDUCT MANUAL PURGING @ 250 RPM (SCREW ROTATION VELOCITY); PURGED MATERIAL FLOW UNUSUAL (NOT STRAIGHT FLOW DURING MANUAL INJECT)
> FOR CHECKING OF NOZZLE HEAD & SCREW SET CONDITION
> MACHINE CAN STILL BE USE BY CUSTOMER BUT UNDER MONITORING

** FOR ALARM OF SCREW RTN PROJECT TRQ LIMIT
> ADJUST (INCREASE) THE BARREL HEATER TEMPERATURE DURING CHANGE MATERIAL OR MANUAL PURGING

SERVICE BY:

1 X. RAMIREZ 3 _____

2 _____ 4 _____

TIME:

Start	End
10 : 30	11 : 05

Total: — hrs. 35 mins.

ALJHON P. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php 13,000.00

Recommendation/Parts for Quotation

> FOR SCREW CLEANING (CHECK SCREW SET CONDITION)	TOTAL SERVICE FEE OF 4 MACHINES SERVICE & CHECKING.