NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2740

Customer: PRICON MICRO ELECTRONICS INC Date: 09 / 25 / 20

Model: FN1000 Machine no. 9A Mfg. yy/mm: 1996.4

Serial Number: S08Q398 Gts.:

Controller: N96 M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

MACHINE TRIPPED-OFF

Action Taken

> TRY POWER ON, BUT CANNOT
> CHECK MAIN SUPPLY OKAY, CHECK ALSO FUSE
> CHECK POWER SUPPLY INPUT 110 V HAVE
> FOUND OUT OUT PUT SUPPLY +15V, -15V, 5V, 12V AND 24V NO HAVE SUPPLY (POWER SUPPLY)
> POSSIBLE PROBLEM POWER SUPPLY
> CUSTOMER REPAIR FIRST OUTSIDE THEN CONTACT NISSEI IF THE POWER SUPPLY ALREADY REPAIR, THEN NISSEI WILL ASSIST

SERVICE BY:

1 X. RAMIREZ 3
2 F. CHING 4

TIME:

Start	End
11 :00	11 :30

Total: - hrs. 30 mins.

AL JHON D. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php 4,000.00

Recommendation/Parts for Quotation