NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2825

Customer: PRICON MICRO ELECTRONICS INC. Date: 11 / 10 / 20

Model: NEX50 - 5E Machine no. 3A Mfg. yy/mm: 2012 . 01

Serial Number: H00511098K1 Gts.: 6917 814 /

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

INSTALLATION OF BALLSCREW (SCREW FWD AND BWD)
(PREV. PROBLEM UNUSUAL SOUND AT INJECTION UNIT)

Action Taken

> INSTALL BALLSCREW AND NEW TIMING BELT, INSTALL FITTINGS
> SET BELT TENSION TO 151 (149-170)
> CONDUCT HEAT-UP
> CHECK FUNCTION, SCREW FWD AND BWD NO UNUSUAL SOUND
> FOR TRIAL WITH PRODUCT
> CONDUCT ALSO PURGING (AUTO), NO UNUSUAL SOUND AND VIBRATION
> CONDUCT TRIAL WITH PRODUCT, MACHINE NO PROBLEM
> MACHINE CAN BE USE

SERVICE BY:

1 X. RAMIREZ 3

2 F. CHING 4

TIME:

Start	End
13 : 00	16 : 30

Total: 3 hrs. 30 mins.

AL JHON D ANONUEVO
Authorized Customer Name & Signature

Service Fee: Php 25,000.00

Recommendation/Parts for Quotation

* TOTAL SERVICE OF 3 DAYS W/ SERVICE REPORT # A2600, A2735 & A2825