NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2852

Customer: PRICON MICROELECTRONICS, INC. Date: 10 / 27 / 20

Model: PN60-5AN Machine no. 28. Mfg. yy/mm: 2009.3

Serial Number: N063107 Gts.: 5497335

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

>> MACHINE CHECKING DUE TO PRODUCT" (SHORT SHOT / SINK MARK PROBLEM)
PROBLEM

Action Taken

>CHECKED INJECTION PRESSURE: 20Mpa [OK']
>CHECKED RESIN INJECTION PRESSURE: Ø (ZERO) @ NEUTRAL POSITION: [OK']
>MINOR OIL LEAK @ INJECTION RAM AREA
>CONDUCT MACHINE TRIAL w/ PRODUCT; PARAMETER ADJUSTMENT
>IF ORIGINAL MOLD INSTALLED AGAIN, TRY TO ADJUST MOLD PARAMETERS

>> NEXT ACTION:
- FOR SCREW CHECKING/CLEANING, NEED TO HAVE A SPARE CHECK RING/SEAT RING W/ HIGH SPECS. (FOR SAFETY PURPOSE ONLY.. IF SCREW BODY/CHECK RING/SEAT RING HAVE DAMAGE)
>> RECOMMENDS TO USE HIGH SPECS. OF BARREL CYLINDER/SCREW SET (SCREW BODY/TORPEDO/CHECK RING/SEAT RING), MACHINE PRONE TO IMMEDIATE WEAR & TEAR USING 380°C ↑ GLASS FIBER MATERIAL

SERVICE BY:

1 J. RUBIO 3 _____
2 X. RAMIREZ 4 _____

TIME:

Start	End
11 :00	130 :

Total: 3 hrs. mins.

Service Fee: Php 7,000.00

AL JHON D. ANONUEVO
Authorized Customer Name & Signature

Recommendation/Parts for Quotation

>CHECK RING [HIGH SPECS. QUOTATION]
>SEAT RING [& STANDARD
>SHUT OFF VALVE FOR INJECTION PRESSURE GAUGE
>GAUGE VALVE