NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3163

Customer: PRICON MICROELECTRONICS INC. **Date:** 08/24/21

Model: PN40-5H **Machine no.** 17A **Mfg. yy/mm:** 2004.09

Serial Number: P04Z009 **Gts.:** 10431565

Controller: NC93T **M/C Service Requested By:** SIR VINCE

Reason for Service / Machine Problem

INSTALLATION OF NEW I/O TERMINAL (OUTPUT)

Action Taken

>TAKE-OUT I/O TERMINAL (OUTPUT)
>INSTALL NEW SPARE OF OUTPUT TERMINAL
>MACHINE TRIAL OUTPUT CONNECTION; OK!
>MACHINE TRIAL W/ CAMERA CONNECTION; OK! (INTERLOCKING TO CAMERA; OK)
>FOR CHECKING OF HARMO ROBOT CONNECTION & INTERLOCK
>MACHINE IS GOOD & CAN BE USE BY CUSTOMER

SERVICE BY:

1 X RAMIREZ 3 _____
2 _____ 4 _____

TIME:

Start	End
10 : 30	13 : 30

Total: 2 hrs. — mins.

VINCE GALINGGANA
Authorized Customer Name & Signature

Service Fee: Php 11,000.00

Recommendation/Parts for Quotation

SERVICE FEE TOTAL OF TWO TIMES MACHINE CHECKING/TROUBLE SHOOTING