NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3332

Customer: PRICON MICROELECTRONICS INC

Date: 10 / 22 / 21

Model: NEX50 III - 5EG Machine no. 22 Mfg. yy/mm: 2016.03

Serial Number: H1051509GK1 Gts.: 9079467

Controller: TACT IV M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

ASSEMBLY OF PULLEY FOR INJECTION CARRIAGE

Action Taken

- ASSEMBLED PULLEY OF INJ. CARRIAGE
- SET BELT TENSION (153 - 169 Hz) - 167 Hz
- CHECKED FUNCTION

SERVICE BY:

1 F. CHING 3

2 R. BANTON 4

TIME:

Start	End
13 : 00	15 : 30

Total: 2 hrs. 30 mins.

ALJHON D ANONUEVO
Authorized Customer Name & Signature

Service Fee: Php 10,000.00

Recommendation/Parts for Quotation

NOTE: TOTAL SERVICE FROM START TO FINISH

- (~~RECOMMEND~~) PLEASE TAKE NOTE: KEEP THE NOZZLE CENTER TO THE MOLD
- INJECTION MUST FIXED ALWAYS