NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3373

Customer: PRICON MICRO ELECTRONICS INC

Date: 10 / 05 / 21

Model: NEX50 III -5EG Machine no. 22 Mfg. yy/mm: 2016.03.

Serial Number: H1051 5096 K1 Gts.: 9079467

Controller: TACT IV M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

- REPLACEMENT OF INJECTION CARRIAGE BALLSCREW.
- MACHINE LEVELLING. (2 MACHINE)

Action Taken

- REPLACED/INSTALLED NEW BALLSCREW (NEW MODEL)
- ~~FOR~~ FOR CONTINUATION OF INSTALLATION, NEED TO REPLACE OLD PULLEY.
- CONDUCTED MACHINE & RE-LEVELLING. (2 MACHINE)

NEX 15 III -2EG m/c 19
H1011 4020 K1
TACT IV
2015.02
Gts. 6723749

SERVICE BY:

1 J. RUBIO 3 _____

2 P. BANTON 4 _____

TIME:

Start	End
15 : 60	16 : 30

Total: 1 hrs. 30 mins.

Service Fee: Php 7,000.00

ALJHON DE CANON VEVO
Authorized Customer Name & Signature

Recommendation/Parts for Quotation

- INJECTION CARRIAGE PULLEY
- CAP SCREW

TOTAL SERVICE FEE FOR MACHINE LEVELLING ONLY.