NISSEI PLASTIC PH. PPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A3692

Customer: PRICON MICROELECTRONICS INC **Date:** 05 / 13 / 22

Model: NEX50 III - 5EG **Machine no.** 22 **Mfg. yy/mm:** 2016. 03

Serial Number: H105150961K1 **Gts.:** 9938993

Controller: TACT IV **M/C Service Requested By:** SIR VINCE / SIR JEOMART

Reason for Service / Machine Problem

5FD05 : SHUTDOWN BY PREVIOUS POWER FAILURE
5FD1B : SHUTDOWN BY PREVIOUS SIG SEGV
(MONITOR BLACKOUT)

Action Taken

- REPLACED NEW CPU MODULE AND SATA BOARD
- INSTALLED PROGRAM , CALIBRATED TOUCH SCREEN
- CHECKED FRONT AND BACKSCREEN DATA
- CHECKED FUNCTION , TRIAL WITH PRODUCT
- MACHINE CAN BE USE

NOTE: FOR REPLACEMENT OF CPU AND AXIS BATTERY

SERVICE BY:

1 F. CHING 3
2 J. PUBIO 4

TIME:

Start	End
10 : 30	12 : 00

Total: 1 hrs. 30 mins.

Authorized Customer Name & Signature

Service Fee: PHP/JPY/USD 10,000.00

Inclusive of Tax: ☐ Exclusive of Tax: ☐

Recommendation/Parts for Quotation

- CPU BATTERY
- AXIS BATTERY

* TOTAL SERVICE FROM START TO FINISH