NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4296

Customer: PRICON MICRO ELECTRONICS INC. **Date:** 12/01/22

Model: PN60-5AN **Machine no.** 21A **Mfg. yy/mm:** 2010.11

Serial Number: E00610001K1 **Gts.:** 6475545

Controller: TACT **M/C Service Requested By:** SIR VINCE / SIR HENRY

Reason for Service / Machine Problem

"5E223: CANNOT INITIALIZE EJECT POS. SENSOR
[MAIN CPU BOARD BATTERY DOWN]

Action Taken

> RE-INSTALL PROGRAM MACHINE BACK-UP DATA
> CHECKED ALL BACKSCREEN PARAMETER DATA
> FOR REPLACEMENT OF CPU BOARD
> MACHINE CAN STILL BE USE BUT MOSTLY ~~ALL~~ ALARM / PROBLEM WILL OCCURS AGAIN

SERVICE BY:

1 X. RAMIREZ 3 _____
2 J. RUBIO 4 _____

TIME:

Start	End
10: 00	10: 15

✓ Henry De Guzman
Authorized Customer Name & Signature

Total: - hrs. 15 mins.

Service Fee: PHP/JPY/USD 5,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐

> PARTS QUOTATION ALREADY SENT LAST TIME.