NISSEI NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Sir KOBAYASHI

Q/S NO: QS 160705001
DATE: July 5, 2016
SERVICE REPORT NO: A0086

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.


Terms of Payment : T/T Remittance 30days After INVOICE date
Validity : August 5, 2016
Machine Model : PS40E2H
Serial Number : P04S035

DESCRIPTION	Q'TY	U/PRICE	TOTAL
1) Screw position Neutral s slowly moving BWD	1	₱10,000	₱10,000 -
Because Oil leak inside Solenoid valve "V240"			
Action taken			
Change Solenoid Valve "V240"			
and			
Change Encoder			

TOTAL	₱10,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.



NPPIS007