MESCO, INC.
RELIANCE COR. BRIXTON STS., BRGY. KAPITOLYO, PASIG CITY 1603
TELS.: 8631-1775 to 84 • FAX: (632) 8631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO Since 1956

QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR Nº 119574

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: CABUYAO
MACHINE: VA1 - II
SERIAL NO.: 1013A
CODE NO.:

SERVICEMAN: ABM/CR6
DATE: 10/20/21
TIME START: 1:00 PM
TIME FINISH: 1:30 PM
TOTAL HRS.:
TRAVELLING HOURS:

JOB COMPLETED: ☒ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☐ NO

REPORTED PROBLEM: SPINDLE WIGGLE

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:
- CHECKED RUN OUT W/ TOOLS - FOUND 0.12mm
- REMOVED TOOLS
- CHECKED TAPER RUN OUT - FOUND 0.022mm
- NEED TO REPLACE SPINDLE CARTRIDGE - 2
- M/C STILL CAN BE USE

☐ PARTS REPLACED ☒ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.
3884-M020-0100	SPINDLE	1

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: N. MENDOZA
POSITION: SR. ENGINEER
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY

MESCO, INC.
RELIANCE COR. BRIXTON STS., BRGY. KAPITOLYO, PASIG CITY 1603
TELS.: 8631-1775 to 84 • FAX: (632) 8631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO Since 1956

QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR Nº 119573

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRI CON
ADDRESS: CABUYAO
MACHINE: VA1-11
SERIAL NO.: 10112A CODE NO.:

SERVICEMAN: ABM/CRG
DATE: 12/20/21
TIME START: 1:30 PM
TIME FINISH: 1:45 pm
TOTAL HRS.: TRAVELLING HOURS:

JOB COMPLETED: ☑ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☐ NO

REPORTED PROBLEM: BACKLASH ON X-AXIS

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:
- BORROWED M/C FROM PRODUCTION
- CHECKED X-AXIS MOVEMENT - FOUND NOISY
- NEED TO REPLACED X-AXIS SUPPORT BEARING - @
- M/C STILL CAN BE USE

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.
NTN: 2A-BST17 X47-1BL X 19/15RS	BEARING	2
6002DD P6	DEEP GROOVE BALL BEARING	1

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: N. MENDOZA
POSITION: SR. ENGINEER
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY