NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Sir KOBAYASHI

Q/S NO: QS 161026 001
DATE: October 26, 2016
SERVICE REPORT NO: A0268

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : T/T Remittance 30days After INVOICE date
Validity : November 26, 2016
Machine Model : UH1000-40 MC#:
Serial Number : P04R005

DESCRIPTION	Q'TY	U/PRICE	TOTAL
Abnormal injection process	1	₱11,500	₱11,500 -
(Screw has abnormal backward movement when in neutral position)			
ACTION TAKEN			
Change Encoder and Base of Encoder			

TOTAL	₱11,500 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

