NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4523

DATE AUG 9, 2016

SERVICE REPORT

CUSTOMER'S NAME PRICON MICRO ELECTRONICS INC.	CUST. SIGNATURE
ADDRESS LISP I CABUYAO LAGUNA PHILIPPINES.	
SERVICE BY MELVIN MORELLA	SERVICE MAN SIGN

1) REPAIR	2) EXAMINATION	3) OVERHAUL	4) FITTING	5) SUPERVISION OF START UP
☐	☐	☐	☑	☐

ACTION TAKEN MODEL : EX-60 SN: 7-002021
- BROKEN POWER SUPPLY CABLE FOR SUB SPOOL GRIP INSIDE LIMIT
- CHANGE 9 CORE WIRE CABLE.
+ TEST RUNNING ON MANUAL AND AUTO MODE. NOW ROBOT IS OKAY AND CAN RUN.

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				
				LABOR AMOUNT	₱ 4,000

TIME STARTED	TIME FINISHED	TOTAL TIME	TRAVEL TIME
9:10	10:50	1.40 HRS	