Parts Name	Actual Picture of Parts
Modification of Ushio Camera interlock for Auto and Semi auto	  
Machine Model	:PE-600/PE-700 — Machine Number : Mold Watching Device
Serial Number	:n/a

NO.	MACHINE NO.	MACHINE MAKER	MACHINE MODEL	SERIAL NUMBER
1	ROTARY MACHINE NO. R1	NISSEI	TNX50RIII5V	TC0519038K1
2	ROTARY MACHINE NO. R2	NISSEI	TNX100RIII12V	TC1019036K1
3	ROTARY MACHINE NO. R3	NISSEI	TNX100RIII12V	TC1019051K1
4	INJECTION MACHINE NO. 30	FANUC	A07B-0524-B001#JGO	A223P0882

QUOTATION SHEET

Date:	2021.04.22
Quotation No:	QG2104019A-46
QR Number:	NA
Reference Date:	2021.04.21
Valid Until:	20 days

G.E.T. Inc,Phil.

www.getinc-jp.com

Email: sales@getinc-jp.com

Global Enginery Technicians Inc.
Victoria Wave Special Economic Zone
Brgy. 186 Mt. Apo Building North Caloocan City
Metro Manila, Philippines 1427
TEL: (02) 5310-7286, (049) 572-2820

Global Engineering & Trading
〒543-0024
#8049-4 Funahashi-cho Tennoji-ku Osaka Japan
TEL: +81-6-6767-5212 FAX: +81-6-6767-5213

CUSTOMER

Company:	**Pricon Microelectronics**
Contact Person:	Mr. Arnold Martinez
Address:	108 Competence Drive, Carmelray Industrial Park 1 SEPZ, Canlubang Calamba City, Laguna Phils.
Telephone Number:	+(63)2-843-0870 loc. 125
Email:	apmartinez@pricon.ph

CONDITIONS

1. Installation: Schedule to be discuss after receipt of PO.
2. Payment Terms: Full payment 10 days after completion.
3. Price is subjected to change without prior notice

SUBJECT: Ushio Camera Interlock wiring Modification P1, P2

NO.	DESCRIPTION	Price(Php/$/¥)	Quantity	Unit	TOTAL
1	**Modification of Ushio Camera interlock for Auto and Semi Auto**	PHP 30,000.00	1	pc	PHP 30,000.00
	1) Cannot operate the Auto and Semi Auto Operation if Camera not in use to avoid mistake set up of the operator.				
	2) For 1 Machine only				
	3) Auto and Semi Auto will be provided by IJM Maker since we cannot modify the program of the Injection Molding Machine.				
	-----NOTHING FOLLOWS-----				

Php 30,000.00 * 4 units = Php 120,000.00

Total Cost: $2197.42