Fitness =  $e^{-lambda * rho^2}$ lambda = 0.00001lambda = 0.0001lambda = 0.0010.8 0.6 Fitness 0.4 0.2 0 50 100 150 200 250 300 Quociente de Rayleigh (rho)