

Non-Contact Infrared Thermometer





32 Memory

Object measurement

Fever Alarm

Specifications

Measurement Object Forehead, Surface, Room

Measurement Distance 1-10cm

Measurement Range 32-45C(89-120.2F)

Measurement accuracy 0.2-0.4(medical)

Resolution 0.1C

Operating Environment

Relative Humidity 15-85%

Operating Temperature 5-45C

Storage Environment

Storage Temperature -20~ +55c

Relative Humidity 15~93%



