







main.asm

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

ORG 0000H

UP:

MOV P2,#0C0H ; 0

ACALL DELAY

MOV P2,#0F9H ; 1

ACALL DELAY

MOV P2,#0A4H ; 2

ACALL DELAY

MOV P2,#0B0H ; 3

ACALL DELAY

MOV P2,#099H ; 4

ACALL DELAY

MOV P2,#092H ; 5

ACALL DELAY

MOV P2,#082H ; 6

ACALL DELAY

MOV P2,#0F8H ; 7

ACALL DELAY

MOV P2,#080H ; 8

ACALL DELAY

MOV P2,#090H ; 9

ACALL DELAY

SJMP UP ; Repeat forever

;-----

; Delay Subroutine

;-----

DELAY:

MOV R5,#10

H1:

MOV R4,#180

H2:

MOV R3,#255

H3:

DJNZ R3,H3

DJNZ R4,H2

DJNZ R5,H1

RET

END