

1 Pictures taken along the Paved National Road Network



Photograph 1-1: Sheer cracks along Kyehooro link 1 at chainage 3+950



Photograph 1-2:Wide cracks along Kyehooro 1 at chainage 4+200



Photograph 1-3:Sheer cracks along Kyehooro link 1 at chainage 4+800



Photograph 1-4: Severe width loss, Potholes, Cracks and edge break along Myanzi – Kiganda road at chainage 103+200.



Photograph 1-5: Ongoing Rehabilitation works along Kiganda - Kitenga road at chainage 108+000 to 109+000.



Photograph 1-6: Potholes, wide cracks and Raveling along Kitenga - Mubende – Lusalira road.



Photograph 1-7: Patches, Potholes and ravelling along Kyegegwa - Kakabara – Kyenjojo road at chainage 232+000 to 234+000



Photograph 1-8: Block cracks along Kampala – Nansana road at chainage 1+000 to 3+000.



Photograph 1-9: Section has severe width loss/Edge drop, Cracks and Potholes along Kampala - Nansana road at chainage 3+000.



Photograph 1-10: Most of the pavement has been completely scrapped off along Salaama road.



Photograph 1-11: Cracks, deep Potholes, and width loss, especially in the first km along Nsambya - Capetown villa road.



Photograph 1-12: Several cracked sections in the sharp bends along Fortportal - Kichwamba - Karugutu road.



Photograph 1-13: Severe cracking along Fortportal - Rwimi road at chainage 288+000 to 288+200.



Photograph 1-14: Severe width loss, Edge break, Wide Cracking and Potholes along Kikorongo - Bwera Mpondwe road.



Photograph 1-15: Wide cracks and Potholes along Namboole Access road.



Photograph 1-16: Pavement severely washed away due to overflow of River Mwamba along Kasese - Kilembe mines road.



Photograph 1-17: Severe edge drop/loss Lwamata - Hoima road at chainage 153+000 to 154+000.



Photograph 1-18: Critical section with Patches & Cracking along Lwamata - Hoima road at chainage 177+000 to 178+000.



Photograph 1-19: Wide cracks along Kabaale - Kaiso road at chainage 38+000 to 49+000.



Photograph 1-20: Patches, Potholes and surface deterioration along Karuma – Olwiyo road.



Photograph 1-21: Patches, Potholes and surface deterioration along Olwiyo – Packwach road.



Photograph 1-22: Patches, Potholes and surface deterioration along Packwach - Nebbi road.



Photograph 1-23: Width loss, edge loss/drop and surface deterioration along Gulu - Atiak - Nimule (Uganda/Sudan border) road.



Photograph 1-24: Width loss and surface deterioration along Arapai - Railway Station road.



Photograph 1-25: Severe surface deterioration, potholes and cracking along Soroti - Dokolo road.



Photograph 1-26: Newly upgraded pavement along Kapchorwa - Suam road.




Photograph 1-27: Newly upgraded pavement along Tirinyi - Pallisa - Kumi road.




Photograph 1-28: Newly upgraded pavement along Hoima - Buliisa - Wanseko road.

2 Pictures taken along the Unpaved National Road Network



Photograph 2-1: Rutting and poor material quality along Mukoko – Birinzi - Ssunga road.




Photograph 2-2: Rutting along Bukulula - Kalungu road.



Photograph 2-3: Severe rutting along Villa Maria - Kalungu road



Photograph 2-4: Severe potholes and gullies along Zengebe-Ferry-Access road.



Photograph 2-5: T - junction at the end Sasira - Namika road.



Photograph 2-6: Deep erosion gullies along Lwampanga - Lwabyata road.




Photograph 2-7: Rutting and other defects along Lwabyata - Kafu road.



Photograph 2-8: Potholes along Bukulula - Kalungu road.



Photograph 2-9: Rutting along Migeera - Nabisweera road.



Photograph 2-10: Potholes and poor formation level along Mukoko - Birinzi - Ssunga road



Photograph 2-11: Bukakata - Old Landing Site road.



Photograph 2-12: Severe rutting along Kikyusa- Bamugolode - Kazwama - Nakasongola road.



Photograph 2-13: Kyabadaza - Kibibi road.



Photograph 2-14: Rutting along Ami - Kidilani road.



Photograph 2-15: Severe Erosion gullies along Ngai – Abok – Otwal - Arom road.



Photograph 2-16: Flooding along Rhino camp-Ogoko - Inde road.



Photograph 2-17: Erosion gullies along Kamdini - Zambia road.



Photograph 2-18: Flooding of River Nile along Tete - Nimule border road.



Photograph 2-19: Erosion gullies along Ngai- Abok – Otwal - Aromo road.



Photograph 2-20: Poor material quality along Nkenda - Bugoye road.



Photograph 2-21: Erosion gullies along Rugendabara - Kasawangari road.



Photograph 2-22: Section of Nyakaliro - Kabagole road.



Photograph 2-23: High road side friction along Katerera - Buhindagye road.



Photograph 2-24: Poor material quality along Kityanza - Bugango access road.



Photograph 2-25: Potholes along Ruhoko - Kabujogera road.



Photograph 2-26: Defects along Kumi-Brooks corner road.




Photograph 2-27: Construction works along Muyembe - Namalu road.



Photograph 2-28: Narrow road width along Ntandi - Kicyo - Bundibugyo road.



Photograph 2-29: The end of Isunga - Bugwara road cut off by the lake.



Photograph 2-30: The end of Kaiso - Tonya cut off by the lake.



Photograph 2-31: Construction works along Masindi - Biiso road.

3 Pictures of Bridges captured On the National Road Network.



Photograph 3-1: B275 along Buseruka - Tonya road is no longer in use.



Photograph 3-2: B264 along Kyenzige - Rugashali - Mabaale road is no longer in use as a new bridge is being constructed.



Photograph 3-3: B071 along Katunguru - Ishasha road with poor waterway condition.



Photograph 3-4: Ongoing replacement works on B082 along Kinyamaseke - Kisinga road.



Photograph 3-5: Waterway condition for B560 along Kisinga – Kyarumba - Kibirizi road.



Photograph 3-6: B158 along Muyembe - Namalu road.



Photograph **3-7**: B873 along Chepsikunya -Girik road.