

1 Pictures taken along the Paved National Road Network



Photograph 1-1: Wide shear cracks along Kyehooro link 1 at chainage 3+950



Photograph 1-2: Sheer cracks along Kyehooro link 1 at chainage 4+800



Photograph 1-3: Severe width loss, potholes, cracks and edge break along Myanzi – Kiganda road at chainage 103+200.



Photograph 1-4: Several cracked sections in the sharp bends along Fortportal - Kichwamba - Karugutu road.



Photograph 1-5: Patches, Potholes and raveling along Kyegegwa - Kakabara – Kyenjojo road at chainage 232+000 to 234+000



Photograph 1-6: Ongoing rehabilitation works along Kiganda - Kitenga road at chainage 108+000 to 109+000.




Photograph 1-7: Wide cracks along Kabaale - Kaiso road at chainage 38+000 to 49+000.



Photograph 1-8: Width loss, edge loss/drop and surface deterioration along Gulu - Atiak - Nimule (Uganda/Sudan border) road.



Photograph 1-9: Severe width loss, Edge break, Wide Cracking and Potholes along Kikorongo - Bwera Mpondwe road.



Photograph 1-10: Wide cracks and Potholes along Namboole Access road.



Photograph 1-11: Pavement severely washed away due to overflow of River Mwamba along Kasese - Kilembe mines road.




Photograph 1-12: Severe edge drop/loss Lwamata - Hoima road at chainage 153+000 to 154+000.




Photograph 1-13: Severe surface deterioration, potholes and cracking along Soroti - Dokolo road.





Photograph 1-14: Newly upgraded pavement along Kapchorwa - Suam road.



Photograph 1-15: ROMDAS surveys on the newly upgraded pavement along Tirinyi - Pallisa - Kumi road.



Photograph 1-16: Newly upgraded pavement along Hoima - Buliisa - Wanseko road.

2 Pictures taken along the Unpaved National Road Network



Photograph 2-1: Severe potholes and gullies along Zengebe-Ferry-Access road.



Photograph 2-2: Severe rutting along Villa Maria - Kalungu road



Photograph 2-3: Deep erosion gullies along Lwampanga - Lwabyata road.



Photograph 2-4: Potholes along Bukulula - Kalungu road.



Photograph 2-5: Defects along Kumi-Brooks corner road.



Photograph 2-6: Kyabadaza - Kibibi road.





Photograph 2-7: Flooding along Rhino camp-Ogoko - Inde road.



Photograph 2-8: Erosion gullies along Ngai- Abok – Otwal - Aromo road.



Photograph 2-9: Flooding of River Nile along Tete - Nimule border road.



Photograph 2-10: High road side friction along Katerera - Buhindagye road.



Photograph 2-11: Poor material quality along Kityanza - Bugango access road.



Photograph 2-12: Poor material quality along Nkenda - Bugoye road



Unnamed Road, Uganda

Latitude
1.58348486°

Longitude
31.10193395°

Local 12:03:56 PM
GMT 09:03:56 AM

Altitude 609.56 meters
Tuesday, 04-27-2021

Photograph 2-13: The end of Kaiso - Tonya cut off by the lake.



Photograph 2-14: The end of Isunga - Bugwara road cut off by the lake.



Photograph 2-15: Mukoko - Birinzi - Ssunga road



Photograph 2-16: Construction works along Masindi - Biiso road.

3 Pictures of Bridges captured on the National Road Network.



Photograph 3-1: B275 Wambabya Bridge along Buseruka - Tonya road is no longer in use.



Photograph 3-2: B071 Rwempunu bridge along Katunguru - Ishasha road with poor waterway condition.



Photograph 3-3: Ongoing replacement works on B082 Kanyampala Upper bridge along Kinyamaseke - Kisinga road.



Photograph 3-4: Waterway condition for B560 along Kisinga – Kyarumba - Kibirizi road.



Photograph 3-5: B158 Sipi bridge along Muyembe - Namalu road.



Photograph 3-6: B873 Girik bridge along Chepsikunya -Girik road.