


<u>2'-1 1/2"</u> 2'-1 1/2"

ROOF FRAMING PLAN

SHEETING

PANELS: 26 Ga. PBr Black

PURLIN LAP









() \triangleleft

ROOF FRAMING	()	LOST COOK	430 NORTH 300	MCKON, C	SHOP/GARAGE
REVISIONS	DESCRIPTION				
	REV DATE:	\triangleleft	\triangleleft	\$ 4	\$ 9




Cory James Price 2021-06-17 11:47:50 -0600

DESIGN: CP DRAFT: BS

CHECK: DATE: 6/ 3/21 JOB # 21045000

GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.



CONNECTION PLATES
FRAME LINE A
DID MARK/PART
1 GC 35







SIDEWALL FRAMING	· · · · · · · · · · · · · · · · · · ·	LOSH COOK	430 NORTH 300 FAST		SHOF/GARAGE	
KEKIOINU	DESCRIPTION					




Cory James Price 2021-06-17 11:47:50 -0600


DESIGN: CP DRAFT: BS CHECK:

DATE: 6/3/21

JOB # 21045000

SHEET OF 12 REV






SIDEWALL SHEETING & TRIM: FRAME LINE A
PANELS: 26 Ga. PBR - Ash Grey

GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.



CONNECTION PLATES
FRAME LINE E
DID MARK/PART







	TOON TOON	430 NORTH 300 EAST	MCKCN,	SHUP/GARAGE	
RIPTION					




Cory James Price 2021-06-17 11:47:51 -0600

DESIGN: CP DRAFT: BS CHECK: DATE: 6/3/21


JOB # 21045000

eet 7 of 12 Rev



CONC. STEM WALL

SIDEWALL SHEETING & TRIM: FRAME LINE E PANELS: 26 Ga. PBR - Ash Grey









S

300 E 84646 JOSH COOK 430 NORTH MORONI,UT



Cory James Price 2021-06-17 11:47:52 -0600

DESIGN: CP DRAFT: BS

DATE: 6/ 3/21

