

## GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

MEMBER FRAME I		
MARK	PART	LENGTH
E-1	E845_14	17'-11 3/4"
E-2	E845_14	17'-11 3 <i>\</i> /4"
G-8	Z825_16	19'-1 1/2"
G-9	Z825_16	19'-1 1/2"
CB-3	0.25_CBL	19'-1 1/2"
CB-3A	0.25_CBL	19'-2 3/4"
		-

CONNECTION PLATES FRAME LINE A


DID MARK/PART

1 GC35










Cory James Price
2021-03-30 17:00:57 -0600

DESIGN: CP DRAFT: SK CHECK:

DATE: 3/29/21

JOB # 21024370

6 12 REV




(Sutrer sith 1 downspaule)

SIDEWALL SHEETING & TRIM: FRAME LINE A
PANELS: 26 Ga. PBR - Country Red

## GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.



CONNECTION PLATES
FRAME LINE C

DID MARK/PART

1 GC35
2 BCC8







SIDEWALL FRAMING		MIKE LAOKANGE	100 SOUTH 400 WFST	MILTORD, O   04/0	
REVISIONS	DESCRIPTION				




Cory James Price 2021-03-30 17:01:14 -0600

DESIGN: CP DRAFT: SK CHECK:

DATE: 3/29/21

TET OF 12 REV





(Gutter with corresponds)

(Gutter with corresponds)

(Signature w


PANELS: 26 Ga. PBR — Country Red





MEMBER	TABLE	
FRAME I	LINE 1	
MARK	PART	LENGTH
EC-1	08B12	12'-1 1/8"
DJ-1	c825_16	10'-0"
DJ-2	c825_16	10'-0"
G-1	z825_16	4'-4"
G-2	c825_16	15'-4"
G-4	z825_16	2'-4 1/2"
G-5	c825_16	17'-4"
JB-1	c825_16	9 11/16"
JB-2	c825_16	1'-7' 11/16"
	16	0 3 /4"

	,	
CON	NECTION	PLATE
FRAI	ME LINE	1
	MARK/P	ART
1	PBC3N	
2	GC35	
7	GC6 75R	














Cory James Price 2021-03-30 17:01:58 -0600

DESIGN: CP DRAFT: SK CHECK:

DATE: 3/29/21



BOLT TABLE
FRAME LINE 3
LOCATION
ER-1/ER-2
Columns/Raf QUAN TYPE DIA LENGTH
12 A325 1/2" 1 1/2"
8 A325 1/2" 1 1/4"

MEMBER		
FRAME I	_INE 3	
MARK	PART	LENGTH
EC-2	c825_16	10'-8 5/8"
EC-3	c825_16	12'-0 11/16"
EC-4	c825_16	10'-8 5/8"
ER-1	C825D14	17'-9 1/4"
ER-2	C825D14	17'-9 1/4"
G-6	z825_14	18'-0"
G-7	z825_16	15'-8 1/2"
CB-1	0.25_CBL	19'-6 1/2"
CB-2	0.25_CBL	18'-10 1/4"

	,
CON	NECTION PLATE
FRAI	ME LINE 3
	MARK/PART
1	BCC3/5
2	GCBP <sup>*</sup>
3	PBC3N
4	PTC-ER1
5	GC35
6	RPI 1-31







 $\mathcal{O}$ 

WE 751

ENDWALL FRAMING		MIKE LAOKANGE	TO SOUTH 400 WF		MILTOKU, OI X4/UI		
REVISIONS	REV DATE: DESCRIPTION	$\forall$	raket	₩	4	8	\$



Cory James Price 2021-03-30 17:02:33 -0600

DESIGN: CP DRAFT: SK CHECK:

DATE: 3/29/21