


## GENERAL NOTES:

- 1. STANDARD CONNECTION FOR ALL ROOF PURLINS TO FRAMES ARE 2 EA. 1/2" A307 BOLTS. STANDARD CONNECTION FOR EAVE STRUTS TO FRAMES ARE 2 EA. 1/2" A325 BOLTS. \*\*EXCEPTIONS WILL BE NOTED IN A BOLT TABLE ON THIS DRAWING\*\*
  IT IS THE RESPONSIBILITY OF THE CONTRACTOR\ERECTOR TO ENSURE THAT ALL BOLT GRADES, DIAMETERS, AND QUANTITIES ARE LOCATED AND INSTALLED AS SPECIFIED.
- 2. SEE DETAILS S49, S50, S51, S52, AND S53 BEFORE INSTALLATION OF ROOF PANELS
- 3. SEAL ALL TRIM LAPS AS NECESSARY TO INSURE WEATHERTIGHTNESS.
- 4. IT IS THE RESPONSIBILITY OF THE ERECTOR TO MAINTAIN PANEL MODULE WIDTH.

LENGTH
_16
_16   19'-9"
_16   18'-7 1/2"
_14   17'-5 3'/4"
_14   17'-5 1/2"
_14   17'-5 3'/4"
_14   17'-5 1/2"
CBL 20'-5 1'/2"
CBL 16'-9"











ROOF FRAMING	CARTER ENTERPRISES INC 912 Industrial RD CEDAR CITY, UT 84721	SHOP/STORAGE
R0(	000	HS

REVISIONS	DESCRIPTION	$\triangle$ 1/13/21 added bdj for door height adj.				
	REV DATE:	1/13/21				
	REV	$\triangleleft$	$\triangleleft$	$\triangleleft$	4	\$ 9



DESIGN: CP DRAFT: BS CHECK: DATE:12/ 2/20



## GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

I MFMRFK	TABLE	
FRAME I	LINE A	
MARK	PART	LENGTH
E-1	E845_14	17'-5 3/4"
E-2	E845_14	17'-5 1/2"
E-3	E845_14	17'-5 3'/4"
G-3	Z825_16	18'-7 1/2"
G-4	Z825 16	19'-9"
G - 5	Z825 16	18'-7 1/2"
CB-2	0.25_CBL	21'-3 1/4"
		·

CONNECTION PLATES FRAME LINE A

DID MARK/PART

1 GC35








Metal Building Systems AC 472									
	O Z								

	S
	ISES 7D 84721
FRAMING	CARTER ENTERPRISES 912 INDUSTRIAL RD CEDAR CITY, UT 8472
$\forall$	
	ENTE USTR OITY,
SIDEWALL	CARTER 912 IND CEDAR
	0 A A D O O O O O O O O O O O O O O O O O


REVISIONS	DESCRIPTION			
	)ATE:			



DESIGN: CP DRAFT: BS CHECK: DATE: 12/ 2/20

JOB # 20103450

SHEET OF 11 REV





(	821					2	)				(Gutter	(3) with 1 d 811	ownspout	s)				4						(5) 
312	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	16'-0"	312
									SIDEWA	ALL SH	HEETIN	G & -	TRIM:	FRAME	E LINE	А								

PANELS: 26 Ga. PBR — Ash Grey

## GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.





MEMBER	TABLE	
FRAME L	INE D	
MARK	PART	LENGTH
DJ-1	c825_16	(15'-3,3/4") <u> </u>
DH-1	c825_16	12,-0,,
E-1	E845_14	17'-5 3/4"
E-3	E845_14	17'-5 3/4"
E-4	E845_14	17'-5 1/2"
G-6	Z825_16	19'-11 1/4"
G-8	Z825_16	4'-10 1/2"
G-9	Z825_16	19'-11 1/4"
CB-3	0.25_CBL	20'-7 3/4"
CB-4	0.25_CBL	21'-7 1/4"


CON	NECTION PLATES
FRAI	ME LINE D
	MARK/PART
1	PBC3N
	EJ1L
3	GC35
4	EJ1R
5	BCC8








NOL	
DOOR HEADER HEIGHT	CAXIEX EZIEXTXISES IZC
	912 INDUSTRIAL RD
	10440



DESIGN: CP DRAFT: BS CHECK: DATE: 12/2/20

от дов # 20103450

6 11 REV 1



BOLT TABLE
FRAME LINE 1
LOCATION QUAN TYPE DIA LENGTH
ER-1/ER-2 8 A325 1/2" 1 1/2"
Columns/Raf 8 A325 1/2" 1 1/4"

 MEMBER TABLE

 FRAME LINE 1

 MARK
 PART
 LENGTH

 EC-1
 c825\_16
 14'-8 5/8"

 EC-2
 c825\_14
 15'-9"

 ER-1
 C825D16
 19'-9 5/16"

 ER-2
 C825D16
 19'-9 5/16"

 G-1
 z825\_16
 12'-0 1/2"

 G-2
 z825\_16
 13'-3 1/2"

 CB-1
 0.25\_CBL
 18'-5 1/4"

	NECTION PLAT
FRAI	ME LINE 1
	MARK/PART
1	BCC3/5
2	GCBP
3	PBC3N
4	PTC-ER1
5	GC35
6	RPS1-31








ENDWALL FRAMING			OFDAR OTT, OT 04/7		SHOP/SIORAGE
REVISIONS	REV DATE: DESCRIPTION	3	4	8	9



DESIGN: CP DRAFT: BS CHECK: DATE: 12/2/20

JOB # 20103450

Theet 7 of 11 Rev



BOLT TABLE
FRAME LINE 5

LOCATION QUAN TYPE DIA LENGTH
ER-2/ER-3 8 A325 1/2" 1 1/2"
Columns/Raf 8 A325 1/2" 1 1/4"

 MEMBER TABLE

 FRAME LINE 5

 MARK
 PART
 LENGTH

 EC-1
 c825\_16
 14'-8 5/8"

 EC-2
 c825\_14
 15'-9"

 ER-2
 C825D16
 19'-9 5/16"

 ER-3
 C825D16
 19'-9 5/16"

 G-1
 z825\_16
 12'-0 1/2"

 G-2
 z825\_16
 13'-3 1/2"


 CB-1
 0.25\_CBL
 18'-5 1/4"

	10 0 1/ 1
CON	INECTION PLATE
FRA	ME LINE 5
	MARK/PART
1	BCC3/5
2	GCBP <sup>*</sup>
3	PBC3N
4	PTC-ER1
5	GC35
1 6	RPS1-31









REV DATE:

DESIGN: CP DRAFT: BS CHECK: DATE: 12/2/20

JOB # 20103450

SHEET OF 11 REV