


MEMBER	TABLE				
Web Depth Web Plate		Outside Flange	Inside Flange		
Mark	Start/End	Thick		W x Thk x Length	W x Thk x Length
RF1-1	15.0/48.0	0.313	233.5	8 x 5/16" x 108.0	8 x 1/2" x 184.0
				8 x 3/8" x 121.9	,
				8 x 3/8" x 52.1	
RF1-2	48.0/33.5	0.313	151.5	8 x 3/8" x 103.5	8 × 1/2" × 272.7
	33.5/22.0	0.250	120.0	8 x 5/16" x 168.0 8 x 1/2" x 275.0	,
RF1-3	22.0/29.0	0.188	240.0	8 x 1/2" x 275.0	8 x 3/8" x 132.0
	29.0/30.0	0.188	35.0	,	8 x 5/16" x 140.5
				1	















DESIGN: ML
DRAFT: NS
CHECK: FL
DATE: 9/17/18

JOB # 8087300

SHEET 3 OF 10 REV





GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

JON BRENNAN 135 W.SHANNON F NAMPA, ID 83687 BRENNAN NON


MEMBER


iAs


2

DESIGN: ML DRAFT: NS CHECK:EL DATE: 9/17/18

^{JOB #} 8087300 5 °F 10









REVISIONS	DESCRIPTION					
	REV DATE:	,	4			
	REV	\forall	\triangle	\$ 	8	8