







GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

<u>1'-0"</u>

RF1-1

GIRT LAPS

10'-0"

20'-0"

DS-1 2

RF2-1

1'-1 1<u>/2"</u> 1'-1 1/2"

2 | G-8

BOLT TABLE: FRAME LINE A

(5)

(H2)—

RF2-1

1'-1 1<u>/2"</u> 1'-1 1/2"

20'-0"

E-3

2 DS-1 2

2 G-18 2

G-17

1'-0"

RF1-1

20'-0"

ST-1(Strut) 2 DS-1 2 2 G-15 2

LOCATION LENGTH QUAN TYPE DIA 3 A325 5/8" 1 1/2" Strut

MEMBER	TABLE	
FRAME I	LINE A	
MARK	PART	LENGTH
DJ-1	c825_16	5'-8"
DS-1	c825_16	5'-0"
E-1	E845_12	19'-11 3/4"
E-2	E845_12	19'-11 1/2"
E-3	E845_12	19'-11 3/4"
G-7	Z825_16	21'-1 1/2"
G-8	Z825_16	
G-9	c825_16	19'-11 3/4"
G-10	Z825_16	22'-3"
G-11	Z825_16	22'-3"
G-12	c825_16	19'-11 1/2"
G-13	Z825 16	22'-3"
G-14	c825_16	19'-11 1/2"
G-15	Z825 16	22'-3"

FRAME	LINE A	
MARK	PART	LENGTH
DJ-1	c825_16	5'-8"
DS-1	c825_16	5'-0"
E-1	E845_12	19'-11 3/4"
E-2	E845_12	19'-11 1/2"
E-3	E845_12	19'-11 3/4"
G-7	Z825_16	19'-11 3/4" 21'-1 1/2"
G-8	Z825_16	2 - /2
G-9	c825_16	19'-11 3/4"
G-10	Z825_16	22'-3"
G-11	Z825_16	22'-3"
G-12	c825_16	19'-11 1/2"
G-13	Z825_16	22'-3"
G-14	c825_16	19'-11 1/2"
G-15	Z825_16	22'-3"
G-16	c825_16	19'-11 1/2"
G-17	Z825_16	$ \angle - / \angle$
G-18	Z825_16	21,-1 1/2",
G-19	c825_16	19'-11 3/4"
ST-1	c835D12	19'-4 1/2"
CB-1	0.44_CBL	23'-1 1/2"
CB-2	0.44_CBL	18'-8 3'/4"

CONNECTION PLATES
FRAME LINE A
DID MARK/PART
1 ESP
2 GC35

220" 230" 230" 230" 230" 230" 230" 230" 230" 230" 230"	821 —	2	(Gutter with 3 o	downspouts)	5	831
		212 212 212 512	512		512 512	

PANELS: 26 Ga. PBR — Charcoal

100'-0" OUT-TO-OUT OF STEEL

<u> 20'-0"</u>

E-2

G-10

SIDEWALL FRAMING: FRAME LINE A

1'-1 1<u>/2"</u> 1'-1 1/2"

2 DS-1 2

1'-1 1<u>/2"</u> 1'-1 1/2"

20'-0"



REV

BUILDING SYSTEMS INC.

METAL BUILDING MANUFACTURERS ASSOCIATION

ACCREDITED

Metal Building Systems
AC 472

 $\subseteq \forall$

 \bigcirc

JAMES SPENCER 249 WEST OLD ROCKY R ROCKY RIDGE, UT 846

SIDEWALL

REVISIONS

RIDGE-645

Cory James Price 2021-05-06 16:05:14 -0600

DESIGN: CP DRAFT: DP DATE: 11/30/20

GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY.
FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

RF1-1

GIRT LAPS

20'-0"

2 DS-1 2

1'-1 1<u>/2"</u> 1'-1 1/2"

BOLT TABLE: FRAME LINE D

20'-0"

E-3

2 DS-1 2

H2)—

1'-1 1<u>/2"</u> 1'-1 1/2"

G-25 🛛

G-17

1'-0"

RF1-1

10'-0"

LOCATION QUAN TYPE DIA LENGTH 3 A325 5/8" 1 1/2" Strut

MEMBER	TABLE	
FRAME I	INF D	
I IVAIVIL I		
MARK	PART	LENGTH
DJ-1	c825_16	5'-8"
DS-1	c825 16	5'-0"
E-1	E845 12	19'-11 3/4"
E-2	E845 12	19'-11 1/2"
E-3	E845 12	19'-11 3'/4"
G-7	Z825 16	21'-1 1/2"

21'-1 1/2" 19'-11 3/4" 22'-3" 19'-11 1/2" 21'-1 1/2" 19'-11 3/4" 21'-1 1/2" 22'-3" 19'-11 1/2" 22'-3" 19'-11 1/2" 21'-1 1/2" 19'-4 1/2" 19'-4 1/2" 18'-8 3/4" c825_16 Z825_16 Z825_16 c825_16 Z825_16 G - 19c825_16 Z825_16 G - 21Z825_16 c825_16 Z825_16 c825_16 G - 25Z825_16 c835D12 0.44_CBL CB-20.44_CBL

CONNECTION PLATES FRAME LINE D DID MARK/PART

G-10 G-13 G-14 G - 17G - 20G-22 G-23 G-24

1 ESP 2 GC35

(5) 2 6 4 (Gutter with 3 downspouts) 22'-0" 22'-0" SIDEWALL SHEETING & TRIM: FRAME LINE D

PANELS: 26 Ga. PBR — Charcoal

100'-0" OUT-TO-OUT OF STEEL

20'-0"

E-2

G - 10

SIDEWALL FRAMING: FRAME LINE D

1'-1 1<u>/2"</u> 1'-1 1/2"

2 DS-1 2

1'-1 1<u>/2"</u> 1'-1 1/2"

20'-0"

20'-0"



BUILDING SYSTEMS INC.

METAL BUILDING MANUFACTURERS ASSOCIATION

MEMBER

ACCREDITED

 $\forall \\ \bigcirc$

 \bigcirc

 \cong

RIDGE -645

ROCKY FUT 846

SPENCEF ST OLD R RIDGE, U

JAMES SPE 249 WEST (ROCKY RIE

FRAMIN

SIDEWALL

RE

Cory James Price 2021-05-06 16:05:15 -0600

DESIGN: CP DRAFT: DP CHECK: DATE: 11/30/20



