Dimensions																
DN	D1	D2		D3		n-d		В	1	fx45°C	Н	K	L1	L2	L3	Е
		PN16	PN10	PN16	PN10	PN16	PN10	В	L	1X43 C	- 11	K	LI	LZ	LO	L
350	520	470	460	429	429	16-28	16-23	26.5	290	4x45°C	530	350	383	360	300	70
400	580	525	515	480	480	16-31	16-28	28	310	4x45°C	590	400	414	389	340	80
450	640	585	565	548	530	20-31	20-23	30	330	4x45°C	650	450	469	444	356	90
500	715	650	620	609	582	20-34	20-28	31.5	350	4x45°C	725	500	521	487	395	100
600	840	770	725	720	682	20-37	20-31	36	390	5x45°C	850	600	572	502	471	120
700	910	840	840	794	794	24-37	24-31	39.5	430	5x45°C	920	700	635	595	546	140
800	1025	950	950	901	901	24-41	24-34	43	470	5x45°C	1035	800	711	680	610	160
900	1125	1050	1050	1001	1001	28-41	28-34	46.5	510	5x45°C	1135	880	963	898	657	150
1000	1255	1170	1160	1112	1112	28-44	28-37	50	550	5x45°C	1265	1000	945	890	<i>7</i> 52	200
1200	1485	1390	1380	1328	1328	30-50	30-41	57	630	5x45°C	1495	1230	1017	968	971	240
1400	1685	1590	1590	1530	1530	34-50	34-44	60	710	5x45°C	1695	1430	1110	1060	1080	280
1600	1930	1820	1820	1750	1750	38-57	38-50	65	790	5x45°C	1940	1630	1210	1160	1220	320